					CHICATON CHI.E	Comments	10.115
L			Search Text	DBs	direct Silling		Definition
	Type	Hits		١	2002/02/11 12:08		
_				USPAT		•	
	1 IS&R			USPAT; US-PGPUB; EPO;	2002/02/11 12:18		
<u> </u>			*****	TPO: DERWENT; IBM TDB			
2	BRS	C67		.040			
		-		USPAT; US-FGFUB; EFU;	2002/02/11 12:14		
_	-			JPO: DERWENT; IBM TDB			
m	BRS	71	1		-		
					12002/02/11 13:52		
L							
4	BRS	361					

BRS	Type	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Detinition	rs
BRS	7.		1	"5646445".PN.	USPAT	2002/02/11 14:03			0
	1 1		1 0		USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2002/02/11 14:06			0
BRS	1 1	L7	12	"5646445"	VT; GPU GPO; VENT	2002/02/11			0
BRS		L28	1063995	(metal adj insert) or nut or bolt or screw	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM	2002/02/11			0
BRS		1.29	537014	L28 and (nut or bolt)	D . H	2002/02/11			0
BRS		L30	28651	L29 and (male or female)	D . H	2002/02/11 14:39			0
BRS		L31	4854	L30 and (hous\$ or package)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2002/02/11 14:40		Truncation Overflow Return string from Server is: 5.0.0.HOU	
BRS		L32	229	L31 and semiconductor	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11 14:52			0
BRS	<b>6</b> 0	L33	0	257/730.cclss	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11 14:53		·	

	Type	#	Hits	Search Text	DBs	Time Stamp Co	Comments	Error Definition	rs
		L34	628	257/730.ccls.	D . I	2002/02/11 14:53			0
	BRS	L35	38	257/730.ccls. and (screw or nut or bolt or rod)	I	2002/02/11 14:57			0
	BRS	L36	71	257/726.ccls. and (screw or nut or bolt or rod)	i	2002/02/11			0
	BRS	L37	65	L36 not L35	D. F	2002/02/11 14:58			0
14	BRS	Т38	37	257/693.ccls. and (screw or nut or bolt or rod)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2002/02/11 15:04			0
15	BRS	L39	52	257/692.ccls. and (screw or nut or bolt or rod)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11 15:06			0
16	BRS	L40	40	L39 not L38	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11 15:04			0
17	BRS	L41	33	257/704.ccls. and (screw or nut or bolt or rod)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11			0

	Type	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	rs
18		1.42	57	257/723.ccls. and (screw or nut or bolt or rod)	USPAT; US-PGPU B; EPO; 2002/0; JPO; JFO; 15:17 ; IBM	2002/02/11 15:17			o
19	BRS	1.43	51		USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	USPAT; US-PGPU B; EPO; DO; JEWENT 15:16 ; IBM			0
20	BRS	L44	4.5	257/698.ccls. and (screw or nut or bolt or rod)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	US-PAT; US-PGPU B; EPO; 2002/02/11 JFO; JERWENT ; IBM TDB			0

	Type	# 1	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	rs
H	BRS	17	10748	470/\$.ccls.	U U U ;	2002/02/11 17:03			0
2	BRS	1.2	1135	L1 and (screw or bolt)	D 1. E	2002/02/11 17:16			0
е	BRS		16	470/6.ccls.	n	2002/02/11			0
4	BRS		258	470/11.ccls.	7. 6	2002/02/11			0
2	BRS	L5	65	L2 and (package or hous\$)	D 15 FI	2002/02/11 18:03		Truncation Overflow. Return string from Server is: 5`320185`	П
9	BRS	L6	1310	L1 and thread\$	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2002/02/11 17:18		Truncation Overflow. Return string from Server is: 5`0`0`THR	-1
7	BRS	L7	H	470/\$.ccls. and semiconductor	1 1	2002/02/11 18:00			0
	BRS		438	L2 and (case or lid)	D. L 1	2002/02/11			0
<u></u>	BRS	1.9	403	18 not 15	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/11 18:04			0